


UPDATED PART: FORK FOR DETACHING LINEN SYSTEM

Models: All G line models, starting from 01/06/2015


Note: New fork with teflon shoe **690000144-01**, compatible with the previous **609000169-01**.

It's easily applicable to all the previous versions of G 35 and G 50 ironers.

For the G 25 ironers through Serial No. 20150531xxxxx, please refer to the replacement kit **X06100**.




OLD FORK



Part No.: 609000169-01

NEW FORK



Part No.: 690000144-01

OLD FORK



Part No.: 609000169-01

Number of old forks 609000169-01 used,
sorted by ironer model.

Model	Nr. of forks
G 14-25	8
G 15-35	8
G 18-35	10
G 21-35	12
G 26-35	15
G 21-50	12
G 26-50	15
G 32-50	18

NEW FORK



Part No.: 690000144-01


Number of new forks 690000144-01 used,
sorted by ironer model.

Model	Nr. of forks
G 14-25	4
G 15-35	4
G 18-35	4
G 21-35	6
G 26-35	6
G 21-50	6
G 26-50	6
G 32-50	7

X06100: REPLACEMENT KIT

Models: G 25 ironers, through Serial No. 20150531xxxxx

Note: Replacement kit to apply the updated version of detaching linen system with forks **690000144-01**.



Part No.:	X06100	Replacement kit for detaching linen system
Bill of Materials:	(1) 609C00445-01	Tube for detaching linen system No. 1
	(2) 609C00443-01	Bracket for detaching linen system No. 2
	(3) 609000442-01	Cap for detaching linen system No. 2
	(4) 609Z00444-01	Plate support for feeler guide shoe No. 1
	(5) 690000144-01	Fork for detaching linen system No. 4

